## Facility or discharge location

Name

ACUSHNET COMPANY, RUBBER DIVISION, PLANT B

Street City 744 Belleville Ave. New Bedford, MA 02745

State/Zip code

Telephone number (including area code) 617-997-2811

MA

0003913

REPORTING PERIOD: FROM

001 DIS

8 6 0 5 0 1 YEAR MO DAY 8 70 5 3 1 YEAR MO DAY

ŤΟ

see INSTRUCTIONS on back

Remarks Titleist Golf Division Laboratory
\* The 12 open container grab samples were
collected over the sampling day, and examined,
then combined into one composite sample for
analysis

(32-37)	T	(3 card only)	QUANT	ITY			(4 cerd only)	CONCENT	RATION			(64-68) FREQUENCY	(69-70)
PARAMETER		(38-45)	(46-53)	(54-61)			(38-45)	CONCENTRATION (46-53) (54-61)		(62-63		33)	SAMPLE
*		MINIMUM	AVERAGE	MAXIMUM	UNITS	NO. EX	MINIMUM	AVERAGE	MAXIMUM	UNITS	EX.	ANALYSIS	TYPE
FLOW	REPORTED	.399	.501	.581	M.G.D.							30/30	24 Hr. %
	PERMIT				,								
OIL + GREASE	REPORTED		.007		LBS/	0						1/30	24 Hr.; compos
	PERMIT , CONDITION		3.3	9.3	Day								
T.S.S.	REPORTED		1.0		LBS/	0						1/30	24 Hr.
	PERM:T CONDITION		9.0	18.0	Day								
C.O.D.	REPORTED							11.4		MG/L	0	1/30	24 Hr. compos
	PERMIT							MONITOR					
рН	REPORTED				]		7.9	8.0	8.5	STD.	6	12/30	24 Hr.
	PERMIT						6.5		80	UNITS			
CR	REPORTED		,					0.05		MG/L 0	J - I	1/90	24 Hr.
	PERMIT CONDITION							0.3					
· <u></u>	REPORTED	*			_	2777				,			
	PERMIT												
	REPORTED					-		,					
	PERMIT									00			
NAME OF PRINCIPAL EXECUTIVE OFFICER		TITLE OF THE OFFICER DATE				I certify that I am familiar with the information contained in this					10	15	N
JEPSON, JOHN		Exec. Vice President & 8 7 0 6 03			report and that to the best of my knowledge and belief such infor-					SNATUR	BOF PRINCIPA	L EXECUTIV	
ST FIRST	Mı		TITLE	YEAR	MO DAY						OFFICE	R OR WTHORI	LU AGENT

## INSTRUCTIONS FOR COMPLETING DISCHARGE MONITORING REPORT

Read these instructions before completing form:

After reading and understanding instructions and forms, please return acknowledgement card.

Sampling and testing procedures should follow those published in 40 C.F.R. 136. These are basically <u>Standard Methods</u> or EPA procedures.

Forms should be completed in triplicate for each discharge with copy each for EPA, state and your records. If the state requires a more frequent submittal than EPA, collate EPA's copies and send as required.

Enter permittee name and facility address, PERMIT NUMBER, discharge number and reporting period. (A separate page is required for each discharge.)

For each parameter monitored during the reporting period, (either as a requirement of the permit or for own information) summarize the data as required in the permit and complete the form as follows:

- 1. Parameter column list parameter name.
- Enter minimum, average and maximum values for quantity and/or concentration under appropriate column headings.
  - a. If frequency is once per month or less, enter the one value under average and leave minimum and maximum blank.
  - b. 1b/day (pounds per day) equal<sub>s</sub> flow (in million gallons per day) times concentration (in mg/l) times 8.34.
    Example: 2.5 MGD x 30 mg/l BOD x 8.34 = 625.5 lb BOD/day
  - c. MGD equals gallons per minute times 1440.
- 3. Enter units as appropriate.

MGD - million gallons per day
lb/day - pounds per day
mg/l - milligrams per liter
SU - standard units for pH
°F - degrees fahrenheit
kg/day - kilograms/day = lb/day
2.2
(other units may be used as necessary)

- Specify the number of samples that exceeded the maximum (and/or minimum, as appropriate) in the columns "NO. EX." If none, enter "O". If there are any violations, send
   a letter of explanation.
- 5. Specify frequency of analysis as number of analyses/
  number days (3/7 is three analyses per every 7 days, 1/7 is weekly,
  1/30 is once a month, 30/30 is daily, 1/90 is quarterly 6 1/180 is
  semiannually) If continuous, enter "CONT"
- 6. Specify sample type ("grab" or "\_hr. composite") If frequency was continuous enter "NA."

Indicate person or laboratory performing analytical work under Remarks.

Print name and title of person responsible for monitoring and reporting and sign and date the form.

Mail state copy to appropriate state agency and EPA copy to

Environmental Protection Agency Permits Branch Box 8127 Boston, MA 02114

When supply of forms will be exhausted within 2 months, send reorder form or reproduce forms yourself.



## ACUSHNET COMPANY RUBBER DIVISION

Manufacturers of Elastomeric Products

June 3, 1987

Mr. George Harding
Permit Compliance Section
Compliance Branch
Water Management Division
Environmental Protection Agency
JFK Federal Building
Boston, MA 02203

RECEIVED

JUN 1 0 1987

**COMPLIANCE BRANCH** 

Gentlemen:

This notice will serve as a letter of explanation for exceeding PH limits as specified on our NPDES permit # MA 0003913661. Six samples had PH readings above the maximum of 8.0 which was due to incoming water from the municipal water system having a PH of 7.9 on the day of testing. This would account for our high readings.

Please contact me if you require further information.

Sincerely,

ACUSHNET COMPANY

John J. Bailey Jr., C.S.P. Manager of Safety and Security

/rg

Enc.